



**MERCEDES C BREAK: 1LRZ353**

|                                   |                   |              |                        |
|-----------------------------------|-------------------|--------------|------------------------|
| Vinnumber:                        | WDD2052371F298368 | Versionname: | 1.6 C 200 D AVANTGARDE |
| First Registrationdate:           | 18/11/2015        | Fiscalpower: |                        |
| Expertise Mileage:                | 101139            | Power Kw:    | 100                    |
| Bodytype:                         |                   | Body color   | Grey                   |
| Gearbox:                          | Automatic         | Paint type   | Metalic                |
| Transmission:                     | Back              | Rims summer  | Aluminium              |
| Fueltype:                         | Diesel            | Oil level    | OK                     |
| Maintenance                       | OK                | Parking lot  | 1509                   |
| Maintenance                       | A1 OVER 319 DAGEN |              |                        |
| Battery functioning               | Yes               |              |                        |
| Number of doors                   | 5                 |              |                        |
| Number of seats                   | 5                 |              |                        |
| Number head rests                 | 5                 |              |                        |
| Rims summer                       | Aluminium         |              |                        |
| Category                          | Passenger Car     |              |                        |
| Oil level                         | OK                |              |                        |
| Registration Certificate Car (BE) | Yes               |              |                        |

**Options**

|                                |                       |                       |            |
|--------------------------------|-----------------------|-----------------------|------------|
| Radio CD                       |                       | Central consol F      |            |
| GPS storage                    | SD                    | Luggage cover         |            |
| GPS storage                    |                       | Front parking sensors |            |
| Windows electric F             |                       | Rear parking sensors  |            |
| Windows electric R             |                       | Type of Tow bar       | No Tow bar |
| Cruise Control                 |                       |                       |            |
| Steering wheel multifunctional |                       |                       |            |
| Seats F heated                 |                       |                       |            |
| Type of headlighting           | Headlighting LED      |                       |            |
| Type of GPS                    | GPS big screen color  |                       |            |
| Type of Lining                 | Lining leather        |                       |            |
| Type of climate control        | Autom climate control |                       |            |

**Limited Technical Inspection**

|                     |    |                     |     |
|---------------------|----|---------------------|-----|
| Airco functioning   | OK | Battery functioning | Yes |
| Tires wear profile  | OK | Power steering      | Yes |
| Idle position       | OK | Sound engine        | OK  |
| Engine startingtime | OK | Clutch test         | OK  |
| Exhaust gass        | OK | Wiper fluid level   | OK  |
| Handbrake           | OK | Transmission        | OK  |
|                     |    | Lighting            | OK  |
|                     |    | Wiperblades         | OK  |

**Degree of wear**

|               |                           |                   |       |                   |
|---------------|---------------------------|-------------------|-------|-------------------|
| Winter tyres: | 225/50/17/98 H LightMetal |                   |       |                   |
|               | Fr.L.                     | Michelin: 7 mm    | Fr.R. | Michelin: 7 mm    |
|               | Re.L.                     | Continental: 6 mm | Re.R. | Continental: 6 mm |

**Assistance equipment**

|                                                      |     |            |      |
|------------------------------------------------------|-----|------------|------|
| Repair kit                                           | Yes | Compressor | Yes  |
| Total cost ex VAT                                    |     |            | 0,00 |
| Outer backrest protection L, Scratch(es), Acceptable |     |            | 0,00 |
| No pictures to display                               |     |            |      |
| Bodywork, Not original part, Acceptable              |     |            | 0,00 |



|                                                      |      |
|------------------------------------------------------|------|
| Alloy rim R R, Scratch(es), Acceptable               | 0,00 |
| No pictures to display                               |      |
| Door frame R L, Scratch(es), Acceptable              | 0,00 |
| No pictures to display                               |      |
| Tires, Not original part, Acceptable                 | 0,00 |
| No pictures to display                               |      |
| Wing F R, Scratch(es), Acceptable                    | 0,00 |
| No pictures to display                               |      |
| Outer backrest protection R, Scratch(es), Acceptable | 0,00 |
| No pictures to display                               |      |
| Alloy rim F L, Scratch(es), Acceptable               | 0,00 |
| No pictures to display                               |      |
| Alloy rim F R, Scratch(es), Acceptable               | 0,00 |
| No pictures to display                               |      |