



OPEL ZAFIRA TOURER: 1NXX508

Vinnumber:	W0LPE9E3XG1106045	Versionname:	1.6 CDTI ECOFLEX 100KW S/S COSMO
First Registrationdate:	13/05/2016	Fiscalpower:	
Expertise Mileage:	70851	Power Kw:	100
Bodytype:		Body color	Dark Blue
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3423
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Seats F heated	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/16/95 V LightMetal			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.
	Re.L.	Continental: 4 mm	Re.R.
		Continental: 4 mm	

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	456,35
Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Protection plate M, Deformed / Strained, E - Replace	74,00



Door R L, Scratch(es), LI - Repair and paint (complete)

318,35



Inner seat cover L, Broken, E - Replace

64,00



Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), Acceptable

0,00

No pictures to display