



FIAT DOBLO CARGO COMBI: SC6142			
Vinnumber:	ZFA26300006J19044	Versionname:	1.3 Multijet 95 Combi SX SWB
First Registrationdate:	25/05/2018	Fiscalpower:	
Expertise Mileage:	49876	Power Kw:	70
Bodytype:		Body color	White
Gearbox:	MAN 5 VIT	Paint type	Opaque
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4605
Number of doors	6		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options			
GPS storage		Central consol F	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	NOT OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Winter tyres:	195/60/16/97 H Steel		
	Fr.L.	Goodyear: 2 mm	Fr.R.
	Re.L.	Goodyear: 5 mm	Re.R.
		Goodyear: 2 mm	Goodyear: 5 mm

Assistance equipment	
Spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	1121,90
Bumper F, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper R, Scratch(es), LI - Repair and paint (complete)	158,85



Door F R, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Boot cover, Missing, E - Replace	37,50
----------------------------------	-------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wheel cover R R, Scratch(es), E - Replace	22,50
---	-------



Seat cover F L, Hole, E - Replace	300,00
-----------------------------------	--------



Windscreen, Repaired, Acceptable	0,00
----------------------------------	------



Door R R, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Internal Boot Lining R, Scratch(es), Smart repair	110,64
---	--------



Wheel cover F R, Scratch(es), E - Replace	22,50
---	-------



Wing R L, Scratch(es), LI - Repair and paint (complete)	231,15
---	--------



Door R L, Scratch(es), LI - Repair and paint (complete)

238,76

