



**TOYOTA GRAND PRIUS+: 1PFK633**

Vinnumber:	<b>JTDZS3EU80J008937</b>	Versionname:	<b>1.8 VVT-I HYBRID ACTIVE AUTO</b>
First Registrationdate:	<b>23/06/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>31486</b>	Power Kw:	<b>73</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Hybrid Petrol</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2527</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/60/16/92 V Steel</b>				
Summer tyres:	Fr.L.	<b>Michelin: 6 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

**Assistance equipment**

Repair kit	<b>No</b>	Compressor	<b>No</b>
------------	-----------	------------	-----------

Total cost ex VAT	<b>1143,22</b>
-------------------	----------------

Luggage space cover, Scratch(es), Acceptable	<b>0,00</b>
--	-------------

<i>No pictures to display</i>	
Interior, Dirty, Acceptable	<b>0,00</b>

<i>No pictures to display</i>	
Protection plate M, Tear, E - Replace	<b>231,90</b>



Wheel cover R R, Scratch(es), E - Replace

30,00



Wing R L, Repaired, Acceptable

0,00



Bonnet, Scratch(es), Acceptable

0,00

*No pictures to display*

Wing R R, Scratch(es), Acceptable

0,00

*No pictures to display*

Tyre repair kit, Missing, E - Replace

210,53



Interior, Damaged, Acceptable

0,00

*No pictures to display*

Wheel cover F R, Scratch(es), Acceptable

0,00

*No pictures to display*

Door F R, Scratch(es), Acceptable

0,00

*No pictures to display*

Internal Boot Lining R, Scratch(es), Smart repair

110,64



Door R R, Scratch(es), Acceptable

0,00

*No pictures to display*

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Door F L, Scratch(es), LI - Repair and paint (complete)

318,35





Wheel cover F L, Scratch(es), E - Replace

30,00

