


VOLKSWAGEN TIGUAN: 1LGB625

Vinnnumber:	WVGZZZ5NZGW032328	Versionname:	2.0 CRTDI 81KW SPORT&STYLE BMOTION
First Registrationdate:	18/09/2015	Fiscalpower:	
Expertise Mileage:	157657	Power Kw:	81
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4831
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	SD	Sun Roof electric	
GPS storage		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	Tow bar fixed
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/17/96 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 2 mm	Re.R.	Michelin: 2 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	0,00
-------------------	------

Door F L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Roof, Chemical polution, 67 - Polish	0,00
--------------------------------------	------

No pictures to display

Wing F R, Scratch(es), Acceptable

0,00



Backrest cover F L, Worn, Acceptable

0,00



Roof pillar R, Scratch(es), Acceptable

0,00

No pictures to display

Rocker panel inner F R, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Dent(s) and scratch(es), Acceptable

0,00



Rear bulkhead lining, Scratch(es), Acceptable

0,00



Door moulding Lower F R, Scratch(es), Acceptable

0,00



Door panel R L, Scratch(es), Acceptable

0,00

No pictures to display

Rear window, Scratch(es), Acceptable

0,00



Bumper F, Scratch(es), Acceptable

0,00



Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display

Door panel R R, Scratch(es), Acceptable

0,00



Windscreen, Repaired, Acceptable

0,00



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Seat cover F L, Worn, Acceptable

0,00



Door R R, Scratch(es), Acceptable

0,00



Wing moulding F R, Scratch(es), Acceptable

0,00



Rocker panel inner R L, Dent(s), Acceptable

0,00

No pictures to display

Door moulding Lower R R, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Dent(s), Acceptable

0,00

No pictures to display

Rocker panel inner F L, Dent(s), Acceptable

0,00

No pictures to display

Centre console, Scratch(es), Acceptable

0,00

No pictures to display