



VOLKSWAGEN Golf: 1HXS455

Vinnumber:	WVWZZZAUZFP554113	Versionname:	GOLF VAR Trendline 90PK
First Registrationdate:	23/10/2014	Fiscalpower:	
Expertise Mileage:	170216	Power Kw:	66
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2522
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
	Tow bar removable

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	211,80
Bonnet, Chemical pollution, Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Bad repair, Acceptable	0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display