



**VOLKSWAGEN Caddy: 1HTP576**

Vinnumber:	<b>WV2ZZZ2KZFX032898</b>	Versionname:	<b>CADDY LIFE 2PLC Dark&amp;Cool 102PK</b>
First Registrationdate:	<b>30/09/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>51574</b>	Power Kw:	<b>75</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2815</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Radio multimedia		Rear parking sensors	
Type of headlighting	<b>Headlighting Halogen</b>	Type of Tow bar	<b>No Tow bar</b>
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>195/65/15/91 T Steel</b>				
Summer tyres:	Fr.L.	<b>Hankook: 4 mm</b>	Fr.R.	<b>Hankook: 4 mm</b>
	Re.L.	<b>Hankook: 4 mm</b>	Re.R.	<b>Hankook: 4 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>1620,51</b>
Wing R L, Scratch(es), LI - Repair and paint (complete)	<b>231,15</b>





Bonnet, Chemical pollution, LI - Repair and paint (complete) 217,56



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 158,85



Rearview mirror housing R, Scratch(es), Smart repair 110,64



Sliding door L, Scratch(es), It - Spot repair 115,56



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 232,88



Sliding door R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), LI - Repair and paint (complete) 362,02



Supplementary brake lights, Scratch(es), E - Replace 33,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 158,85

