



VOLKSWAGEN PASSAT: 1LJZ940

Vinnumber:	WVWZZZ3CZGE070698	Versionname:	2.0 TDI HIGHLINE MSQ
First Registrationdate:	8/10/2015	Fiscalpower:	
Expertise Mileage:	200075	Power Kw:	110
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	IN 2900 KM	Parking lot:	2211
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Front parking sensors
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	NOT OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/17/94 V LightMetal				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	2626,05
-------------------	----------------

Interior, Not original part, P - Check	0,00
--	-------------




Bumper grille, Broken, E - Replace

32,40



Door R R, Dent(s), LI - Repair and paint (complete)

462,35



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Floor covering F L, Burned, Smart repair

64,32



Ignition key, Missing, E - Replace

150,00



Interior, Not original part, P - Check

0,00



Bumper moulding F, Broken, E - Replace

14,40



Backrest cover F L, Worn, P - Check

0,00



Bodywork, Not original part, P - Check

0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F, Broken, Le - Replace and paint

735,00



Bumper grille F L, Broken, E - Replace

32,40



Grill, Broken, E - Replace

225,40



Wing R R, Dent(s), Acceptable

0,00

No pictures to display

Wing F L, Dent(s), LI - Repair and paint (complete)

316,18



Wing R L, Dent(s), Acceptable

0,00

No pictures to display

Bumper R, Dent(s), LI - Repair and paint (complete)

307,80



Floor covering F L, Stain, Cleaning

25,00



Bumper moulding F L, Broken, E - Replace

14,40



Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper spoiler F, Broken, E - Replace

42,00



Bumper moulding F M, Broken, E - Replace

14,40

