



TOYOTA GRAND PRIUS+: 1SXA508

Vinnumber:	JTDZS3EU30J014838	Versionname:	1.8 VVT-i Hybrid Comfort
First Registrationdate:	3/08/2017	Fiscalpower:	
Expertise Mileage:	56247	Power Kw:	73
Bodytype:		Body color:	Silver
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2302
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		
Head-up Display			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/92 V Steel			
Summer tyres:	Fr.L. Michelin: 4 mm	Fr.R. Michelin: 4 mm	
	Re.L. Michelin: 4 mm	Re.R. Michelin: 4 mm	

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1298,14
--------------------------	----------------



Door panel F L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Bodywork, Not original part, Acceptable	0,00
--	-------------

No pictures to display

Wing F L, Scratch(es), Acceptable	0,00
--	-------------

<i>No pictures to display</i>		
Rear Panel Internal Lining, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Boot cover, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Dashboard, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Rear bulkhead lining, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Steering wheel, Worn, E - Replace		1205,14
		
Mirror side blinker R, Waterinfiltration, E - Replace		30,00
		
Wing R R, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Wheel cover R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door panel R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Interior, Not original part, P - Check		0,00
<i>No pictures to display</i>		
Bonnet, Stone chip(s), Acceptable		0,00
<i>No pictures to display</i>		
Centre console, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Ceiling, Unclasp(ed), Repair/replace (lump sum)		63,00
