



VOLKSWAGEN Passat: 1HJV555

Vinnnumber:	VWZZZ3CZEE167653	Versionname:	PASSAT VAR Comfortline BMT 105PK
First Registrationdate:	5/08/2014	Fiscalpower:	
Expertise Mileage:	135568	Power Kw:	77
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2608
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage	HD	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar fixed
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	NOT OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/16/97 W LightMetal				
Summer tyres:	Fr.L.	Dunlop: 3 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1237,47
Bumper F, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)	301,68



Wing F R, Scratch(es), 67 - Polish 0,00

No pictures to display


Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), E - Replace 0,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00





Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Door F R, Bad repair, Acceptable 0,00



Door R R, Dent(s), Acceptable 0,00

No pictures to display

Rocker panel inner R R, Dent(s), LI - Repair and paint (complete) 115,56

