



SEAT ATECA: 1RCR641

Vinnumber:	VSSZZZ5FZH6507562	Versionname:	2.0 TDI 190 PS S/S XCELLENCE DCT 4WD
First Registrationdate:	16/11/2016	Fiscalpower:	
Expertise Mileage:	126829	Power Kw:	140
Bodytype:		Body color:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3830
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	SD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining Alcantara		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

255/40/19/100 V LightMetal				
Winter tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm






Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 190,56

Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)	115,56
	
Instrument panel cover, Glue residues, Acceptable	0,00
	
Boot carpet, Stain, Cleaning	25,00
	
Ignition key, Not functioning (well), Repair/replace (lump sum)	0,00
	
Electricity circuit, Maintenance, P - Check	0,00
	
Protection plate M, Hole, E - Replace	50,00
