



**VOLKSWAGEN PASSAT VARIANT: 1LRF007**

Vinnumber:	<b>WVWZZZ3CZGE108467</b>	Versionname:	<b>1.6 TDI VARIANT COMFORTLINE</b>
First Registrationdate:	<b>13/11/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>152956</b>	Power Kw:	<b>88</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4411</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>SD</b>	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>Tow bar fixed</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>215/60/16/99 H LightMetal</b>				
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>3809,84</b>
<b>Bumper grille, Broken, E - Replace</b>	<b>32,40</b>



Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)

115,56




Bumper R, Crack, LI - Repair and paint (complete)

211,80




Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Roof, Chemical pollution, LI - Repair and paint (complete)

481,50




Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Tailgate, Dent(s), LI - Repair and paint (complete)

301,68



Wing F L, Scratch(es), LI - Repair and paint (complete)

220,18



Door R L, Dent(s), Acceptable

0,00

No pictures to display


Rearview mirror L complete, Broken, Le - Replace and paint

283,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

366,35



Door F L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover R L, Stain, Cleaning 25,00



Roof pillar L, Dent(s), Acceptable 0,00

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Rocker panel inner R L, Dent(s), LI - Repair and paint (complete) 115,56




Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08





Roof pillar R, Dent(s), Acceptable

0,00

No pictures to display