



VOLKSWAGEN Sharan: EW6617

Vinnnumber:	VVWZZZ7NZDV018399	Versionname:	SHARAN Highline BMT DSG 170PK Aut.
First Registrationdate:	19/11/2012	Fiscalpower:	
Expertise Mileage:	137474	Power Kw:	125
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2525
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Sun Roof electric	
GPS storage	HD	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/98 V LightMetal				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		


Total cost ex VAT	4099,61
Roof, Hail damage, PDR - Hail	650,00



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Dent(s), Acceptable 0,00

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

264,21



Roof pillar L, Dent(s), Acceptable

0,00

No pictures to display

Roof pillar R, Dent(s), PDR - Paintless dent repair

122,40



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

362,02



Rear spoiler, Dent(s), LI - Repair and paint (complete)

115,56



Bonnet, Dent(s), PDR - Paintless dent repair

122,40





Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)


95,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)


369,84





Windscreen, Stone chip(s), Windscreen repair

58,80



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02

