



AUDI Q5: 1LRS639

Vinnnumber:	WAUZZZ8R3GA080755	Versionname:	2.0 TDI 140KW S TRONIC QUATTRO
First Registrationdate:	17/11/2015	Fiscalpower:	
Expertise Mileage:	175862	Power Kw:	140
Bodytype:		Body color:	Silver
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2627
Number of doors:	5		
Number of seats:	5		
Number head rests:	6		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/65/17/104 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1484,99
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	254,16



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Outer backrest protection L, Tear, E - Replace 20,00




Windscreen, Broken, E - Replace 0,00



Backrest cover F L, Worn, Acceptable 0,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16





Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), LI - Repair and paint (complete) 264,21



Trunk lid covering R, Scratch(es), Smart repair 110,64



Reflector, Broken, E - Replace 54,00



Door F L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s), PDR - Paintless dent repair 63,00



Rearview mirror housing L, Scratch(es), 67 - Polish 0,00



Bonnet, Chemical polution, 67 - Polish 0,00

No pictures to display

Roof, Dent(s), PDR - Paintless dent repair 82,80

