



AUDI A3 SPORTBACK: 1LUE342

Vinnumber:	WAUZZZ8V0GA088826	Versionname:	1.6 TDI ULTRA ATTRACTION SPORTBACK
First Registrationdate:	7/12/2015	Fiscalpower:	
Expertise Mileage:	106804	Power Kw:	81
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4527
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Rear parking sensors	
GPS storage		Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	3015,03
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R L, Chemical polution, LI - Repair and paint (complete)

308,20



Boot cover, Missing, E - Replace

50,00




Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00





Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Wing F R, Chemical polution, 67 - Polish 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Chemical polution, 67 - Polish 0,00

No pictures to display

Rear spoiler, Chemical polution, 67 - Polish 0,00

No pictures to display

Sill outer L, Scratch(es), LI - Repair and paint (complete) 310,50




Internal Boot Lining R, Scratch(es), Acceptable 0,00



Rear window, Scratch(es), E - Replace 370,00





Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00




Door R R, Chemical polution, LI - Repair and paint (complete)

318,35



Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Wing R R, Chemical polution, 67 - Polish

0,00

No pictures to display

Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Dent(s), PDR - Paintless dent repair

82,80

