



VOLVO XC60: 1LAH415

Vinnumber:	VV1DZARC1G2814945	Versionname:	2.0 D3 2WD MOMENTUM
First Registrationdate:	31/07/2015	Fiscalpower:	
Expertise Mileage:	132915	Power Kw:	110
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2332
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/60/18/103 V LightMetal				
Summer tyres:	Fr.L.	Continental: 2 mm	Fr.R.	Continental: 2 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 1393,82

Wing R R, Dent(s), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Rear spoiler, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Protection plate M, Deformed / Strained, E - Replace	74,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00



Door panel R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Chemical polution, 67 - Polish	0,00
<i>No pictures to display</i>	
Luggage space cover, Missing, E - Replace	288,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------





Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Door R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Door panel R L, Tear, Smart repair 110,64



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), 67 - Polish 0,00

No pictures to display