



AUDI A3 SPORTBACK: 1LPU865

| | | | |
|------------------------------------|--------------------------|--------------|---|
| Vinnumber: | WAUZZZ8V4GA067249 | Versionname: | 1.6 TDI ULTRA ATTRACTION SPORTBACK |
| First Registrationdate: | 9/11/2015 | Fiscalpower: | |
| Expertise Mileage: | 95879 | Power Kw: | 81 |
| Bodytype: | | Body color: | Silver |
| Gearbox: | MAN 6 VIT | Paint type: | Metallic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3328 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|------------------------------|-------------------|
| Windows electric F | Central consol F | |
| Windows electric R | Luggage cover | |
| Cruise Control | Rear parking sensors | |
| Steering wheel multifunctional | Type of Tow bar | No Tow bar |
| Radio multimedia | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | No GPS | |
| Type of Lining | Lining fabrics | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| 205/55/16/91 V LightMetal | | | | |
| Summer tyres: | Fr.L. | Michelin: 3 mm | Fr.R. | Michelin: 3 mm |
| | Re.L. | Michelin: 3 mm | Re.R. | Michelin: 3 mm |

Assistance equipment

| | | | |
|--|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|--|-------|
| Total cost ex VAT | 63,00 |
| Wing F L, Dent(s), PDR - Paintless dent repair | 63,00 |



| | |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper F, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |