



AUDI A6 Allroad: 1HDU579

Vinnumber:	WAUZZZ4G5EN169706	Versionname:	A6 ALLROAD Quattro S-tr.204PK Aut.
First Registrationdate:	26/06/2014	Fiscalpower:	
Expertise Mileage:	173944	Power Kw:	150
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	IN 22900 KM	Parking lot:	3720
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/55/18/104 Y LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	480,68
Boot carpet, Stain, Cleaning	25,00



Wing moulding F R, Scratch(es), E - Replace

17,28



Bumper R, Deformed / Strained, Le - Replace and paint

0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing moulding F L, Scratch(es), E - Replace

17,28



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Bumper moulding R, Deformed / Strained, E - Replace

0,00



Door frame R L, Dent(s), It - Spot repair

115,56



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00

