



**AUDI Q5: 1NBR799**

Vinnumber:	<b>WAUZZZ8R5GA076903</b>	Versionname:	<b>2.0 TDI 120KW S TRONIC QUATTRO</b>
First Registrationdate:	<b>13/01/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>117129</b>	Power Kw:	<b>120</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>4 Weel</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4222</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining semi-leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>23/65/17/104 H LightMetal</b>				
Winter tyres:	Fr.L.	<b>Continental: 7 mm</b>	Fr.R.	<b>Continental: 7 mm</b>
	Re.L.	<b>Goodyear: 8 mm</b>	Re.R.	<b>Goodyear: 8 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>2102,14</b>
Reflector, Broken, E - Replace	<b>104,70</b>



Wing F R, Dent(s) and scratch(es), Acceptable

0,00



Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable

0,00

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16



Bumper R, Hole, Le - Replace and paint

766,80



Rear spoiler, Chemical polution, 67 - Polish

0,00

No pictures to display

Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Dent(s), Acceptable

0,00

No pictures to display

Boot cover, Missing, E - Replace

10,00



Door F R, Dent(s), PDR - Paintless dent repair 82,80



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 369,84



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 513,84



Door R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display