



**BMW 3: 1HZR625**

|                                    |                          |              |                                  |
|------------------------------------|--------------------------|--------------|----------------------------------|
| Vinnumber:                         | <b>WBA3Y11020D451060</b> | Versionname: | <b>3 GRAN TURISMO 318d 143PK</b> |
| First Registrationdate:            | <b>7/11/2014</b>         | Fiscalpower: |                                  |
| Expertise Mileage:                 | <b>73768</b>             | Power Kw:    | <b>105</b>                       |
| Bodytype:                          |                          | Body color:  | <b>White</b>                     |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Opaque</b>                    |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Aluminium</b>                 |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                        |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2225</b>                      |
| Number of doors:                   | <b>5</b>                 |              |                                  |
| Number of seats:                   | <b>5</b>                 |              |                                  |
| Number head rests:                 | <b>5</b>                 |              |                                  |
| Rims summer:                       | <b>Aluminium</b>         |              |                                  |
| Category:                          | <b>Passenger Car</b>     |              |                                  |
| Oil level:                         | <b>OK</b>                |              |                                  |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                  |

**Options**

|                                |                                  |                      |                   |
|--------------------------------|----------------------------------|----------------------|-------------------|
| Radio CD                       |                                  | Central consol F     |                   |
| GPS storage                    |                                  | Luggage cover        |                   |
| GPS storage                    | <b>HD</b>                        | Rear parking sensors |                   |
| Windows electric F             |                                  | Type of Tow bar      | <b>No Tow bar</b> |
| Windows electric R             |                                  |                      |                   |
| Cruise Control                 |                                  |                      |                   |
| Steering wheel multifunctional |                                  |                      |                   |
| Radio multimedia               |                                  |                      |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>      |                      |                   |
| Type of GPS                    | <b>GPS big screen color</b>      |                      |                   |
| Type of Lining                 | <b>Lining artificial leather</b> |                      |                   |
| Type of climate control        | <b>Autom climate control</b>     |                      |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                          |       |                          |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| <b>225/55/17/97 W LightMetal</b> |       |                          |       |                          |
| Summer tyres:                    | Fr.L. | <b>Bridgestone: 4 mm</b> | Fr.R. | <b>Bridgestone: 4 mm</b> |
|                                  | Re.L. | <b>Bridgestone: 3 mm</b> | Re.R. | <b>Bridgestone: 3 mm</b> |

**Assistance equipment**

|  |            |            |            |
|--|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

|   |               |
|---|---------------|
| <b>Total cost ex VAT</b>  | <b>903,68</b> |
| <b>Alloy rim F L, Scratch(es), LI - Repair and paint (complete)</b> | <b>95,00</b>  |



Door F R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display


Seat cover F L, Worn, Acceptable 0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete) 290,08



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Sill outer L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80





|                                    |      |
|------------------------------------|------|
| Door R R, Scratch(es), 67 - Polish | 0,00 |
|------------------------------------|------|

*No pictures to display*

|                                   |      |
|-----------------------------------|------|
| Door F L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

*No pictures to display*