



**BMW 3 GRAN TURISMO: 1NSA693**

Vinnumber:	<b>WBA8Y51020G431094</b>	Versionname:	<b>2.0 318D (100KW) GRAN TURISMO</b>
First Registrationdate:	<b>13/04/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>162017</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4733</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Front parking sensors	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	<b>Tow bar fixed</b>
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining artificial leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/55/17/97 Y LightMetal</b>				
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 4 mm</b>	Re.R.	<b>Continental: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>1503,48</b>
<b>Wheel cover R L, Not original part, E - Replace</b>	<b>30,00</b>



Bonnet, Scratch(es), Acceptable

0,00

*No pictures to display*

Alloy rim R L, Chemical polution, LI - Repair and paint (complete)

95,00



Door panel F R, Scratch(es), Acceptable

0,00

*No pictures to display*

Alloy rim R R, Chemical polution, LI - Repair and paint (complete)

95,00



Wheel cover F R, Not original part, E - Replace

30,00



Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20



Wheel cover F L, Not original part, E - Replace

30,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F R, Chemical polution, LI - Repair and paint (complete)

95,00



Bumper R, Dent(s), LI - Repair and paint (complete)

211,80



Steering wheel, Worn, Acceptable

0,00

No pictures to display

Tailgate, Dent(s), LI - Repair and paint (complete)

301,68



Alloy rim F L, Chemical polution, LI - Repair and paint (complete)

95,00

