



OPEL Vivaro 2900: 1EMX555

Vinnumber:	WOLF7B086DV603412	Versionname:	VIVARO 2900 B/F MWB L2H1 DPF(EU5) 90PK
First Registrationdate:	25/01/2013	Fiscalpower:	
Expertise Mileage:	210542	Power Kw:	66
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV05
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Type of Tow bar	Tow bar fixed
Windows electric F		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	No GPS	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/65/16/105 T Steel				
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	886,90
Wheel cover R L, Missing, E - Replace	22,50



Bumper F, Scratch(es), Smart repair	110,64
--	---------------



Sill outer L, Dent(s), LI - Repair and paint (complete) 232,88



Bodywork, Not original part, Acceptable 0,00

No pictures to display

Wheel cover R R, Missing, E - Replace 22,50



Sill outer R, Dent(s), LI - Repair and paint (complete) 232,88



Bumper R, Dent(s), Acceptable 0,00

No pictures to display

Foglight R, Broken, E - Replace 115,50



Ignition key, Missing, E - Replace 150,00

No pictures to display