


**BMW 5 TOURING: 1RBE275**

|                                    |                          |              |                                 |
|------------------------------------|--------------------------|--------------|---------------------------------|
| Vinnumber:                         | <b>WBA5L11030G718017</b> | Versionname: | <b>2.0 518D (110KW) TOURING</b> |
| First Registrationdate:            | <b>3/11/2016</b>         | Fiscalpower: |                                 |
| Expertise Mileage:                 | <b>157412</b>            | Power Kw:    | <b>110</b>                      |
| Bodytype:                          |                          | Body color:  | <b>Grey</b>                     |
| Gearbox:                           | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>                  |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Aluminium</b>                |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                       |
| Maintenance:                       | <b>OK</b>                | Parking lot: | <b>3831</b>                     |
| Battery functioning:               | <b>Yes</b>               |              |                                 |
| Number of doors:                   | <b>5</b>                 |              |                                 |
| Number of seats:                   | <b>5</b>                 |              |                                 |
| Number head rests:                 | <b>5</b>                 |              |                                 |
| Rims summer:                       | <b>Aluminium</b>         |              |                                 |
| Category:                          | <b>Passenger Car</b>     |              |                                 |
| Oil level:                         | <b>OK</b>                |              |                                 |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                 |

**Options**

|                                |                                  |
|--------------------------------|----------------------------------|
| Radio CD                       | Central consol F                 |
| Windows electric F             | Luggage cover                    |
| Windows electric R             | Front parking sensors            |
| Cruise Control                 | Rear parking sensors             |
| Steering wheel multifunctional |                                  |
| Seats F heated                 |                                  |
| Type of headlighting           | <b>Headlighting Xenon</b>        |
| Type of GPS                    | <b>GPS big screen color</b>      |
| Type of Lining                 | <b>Lining artificial leather</b> |
| Type of climate control        | <b>Autom climate control</b>     |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                       |       |                       |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| <b>225/55/17/92 H LightMetal</b> |       |                       |       |                       |
| Summer tyres:                    | Fr.L. | <b>Michelin: 4 mm</b> | Fr.R. | <b>Michelin: 4 mm</b> |
|                                  | Re.L. | <b>Michelin: 5 mm</b> | Re.R. | <b>Michelin: 5 mm</b> |

**Assistance equipment**

|   |            |            |                |
|---|------------|------------|----------------|
| Repair kit                              | <b>Yes</b> | Compressor | <b>Yes</b>     |
| Total cost ex VAT                       |            |            | <b>1659,73</b> |
| Bumper R, Crack, Le - Replace and paint |            |            | <b>766,80</b>  |



Rearlight R tailgate, Crack, E - Replace

111,21



Bonnet, Scratch(es), Acceptable

0,00

*No pictures to display*

Ignition key, Missing, E - Replace

150,00

*No pictures to display*

Bumper F L, Scratch(es), It - Spot repair

115,56



Rearlight R , Crack, E - Replace

132,00



Tailgate, Dent(s), LI - Repair and paint (complete)

362,02



Reflector, Crack, E - Replace

22,14



Windscreen, Stone chip(s), Windscreen repair

0,00



Rearview mirror basis L, Scratch(es), Acceptable

0,00

*No pictures to display*