


BMW 4 GRAN COUPE: 1LSN381

Vinnumber:	WBA4E71060GR81398	Versionname:	2.0 418D (110KW) GRAN COUPE
First Registrationdate:	24/11/2015	Fiscalpower:	
Expertise Mileage:	116588	Power Kw:	110
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3407
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Seats F heated	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/18/92 MS LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			564,44
Bonnet, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)			95,00



Alloy rim F L polished, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Bumper F L, Scratch(es), Acceptable	0,00
-------------------------------------	------

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Windscreen, Repaired, Acceptable	0,00
----------------------------------	------



Bumper R, Broken, LI - Repair and paint (partial)	97,00
---	-------



Wing R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Alloy rim R L polished, Deformed / Strained, E - Replace	277,44
--	--------

