


**SKODA Octavia: 1HYP441**

Vinnumber:	<b>TMBJG7NE1F0102087</b>	Versionname:	<b>OCTAVIA COMBI GreenLine Ambition 110PK</b>
First Registrationdate:	<b>30/10/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>125409</b>	Power Kw:	<b>81</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1213</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	<b>No Tow bar</b>
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/65/15/91 H Steel</b>			
Summer tyres:	Fr.L.	<b>Uniroyal: 3 mm</b>	Fr.R.	<b>Uniroyal: 3 mm</b>
	Re.L.	<b>Uniroyal: 3 mm</b>	Re.R.	<b>Uniroyal: 3 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	0,00
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rocker panel inner R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Bad repair, Acceptable	0,00



<b>Seat cover F L, Stain, Acceptable</b>	<b>0,00</b>
<i>No pictures to display</i>	
<b>Windscreen, Repaired, Acceptable</b>	<b>0,00</b>
<i>No pictures to display</i>	
<b>Sill outer L, Scratch(es), Acceptable</b>	<b>0,00</b>
<i>No pictures to display</i>	
<b>Door R L, Dent(s), Acceptable</b>	<b>0,00</b>
<i>No pictures to display</i>	
<b>Door R R, Dent(s), Acceptable</b>	<b>0,00</b>
<i>No pictures to display</i>	
<b>Wing R R, Repaired, Acceptable</b>	<b>0,00</b>
<i>No pictures to display</i>	
<b>Wheel cover R R, Scratch(es), Acceptable</b>	<b>0,00</b>
<i>No pictures to display</i>	