



**BMW 5: VQ8232**

Vinnumber:	<b>WBA5K31030D485871</b>	Versionname:	<b>5 TOURING 530dXAS 258PK Aut.</b>
First Registrationdate:	<b>15/11/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>188126</b>	Power Kw:	<b>190</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4231</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	<b>HD</b>	Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	<b>No Tow bar</b>
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		
Head-up Display			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/55/17/97 W LightMetal</b>			
Summer tyres:	Fr.L. <b>Continental: 4 mm</b>	Fr.R. <b>Continental: 4 mm</b>	
	Re.L. <b>Michelin: 3,5 mm</b>	Re.R. <b>Michelin: 3,5 mm</b>	

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>578,56</b>
--------------------------	---------------

<b>Door R R, Repaired, P - Check</b>	<b>0,00</b>
--------------------------------------	-------------



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

268,56



Door F R, Repaired, P - Check

0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L, Scratch(es), Acceptable

0,00

*No pictures to display*

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Door panel F L, Dirty, Cleaning

25,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00

