


BMW 5 BERLINE: 1LKL943

Vinnumber:	WBA5E71040G157257	Versionname:	2.0 520D (120KW) XDRIVE AUTO
First Registrationdate:	13/10/2015	Fiscalpower:	
Expertise Mileage:	133842	Power Kw:	120
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3115
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Front parking sensors	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 Y LightMetal				
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Number of charging cables (normal)	0	Runflat	Yes
Number of charging cables (rapid charge)	0		

Total cost ex VAT 1960,34

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), It - Spot repair 115,56



Bumper R, Hole, Le - Replace and paint

766,80



Door F R, Scratch(es), LI - Repair and paint (complete)

382,02



Bonnet, Chemical polution, 67 - Polish

0,00



Wing R L, Scratch(es), LI - Repair and paint (complete)

369,84



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Bumper F R, Scratch(es), It - Spot repair

115,56

