



VOLKSWAGEN PASSAT VARIANT: 1LJK488

Vinnumber:	WVWZZZ3CZGE077064	Versionname:	1.6 TDI VARIANT COMFORTLINE
First Registrationdate:	5/10/2015	Fiscalpower:	
Expertise Mileage:	167988	Power Kw:	88
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3402
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
	Tow bar fixed

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/16/99 V LightMetal				
Summer tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	518,64
Wing R L, Dent(s), It - Spot repair	115,56




Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Seat cover R, Stain, Cleaning 50,00



Bonnet, Chemical pollution, LI - Repair and paint (complete) 290,08



Ceiling, Stain, Acceptable 0,00

No pictures to display

Seat cover F R, Stain, Acceptable 0,00

No pictures to display

Bumper grille, Crack, E - Replace 0,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Crack, Le - Replace and paint 0,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Repaired, Acceptable 0,00

No pictures to display

Door R L, Dent(s), PDR - Paintless dent repair 63,00

