



**VOLKSWAGEN Golf: 1JFG074**

Vinnumber:	<b>WVWZZZAUZFP573407</b>	Versionname:	<b>GOLF VAR Trendline 105PK</b>
First Registrationdate:	<b>2/12/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>180288</b>	Power Kw:	<b>77</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3611</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage	<b>SD</b>	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>No Tow bar</b>
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		
Adaptive cruise control			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>195/65/15/91 H LightMetal</b>				
Summer tyres:	Fr.L.	<b>Hankook: 5 mm</b>	Fr.R.	<b>Hankook: 5 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>830,36</b>
<b>Bonnet, Scratch(es), Acceptable</b>	<b>0,00</b>

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Wing R L, Scratch(es), It - Spot repair 115,56

No pictures to display

Backrest cover F L, Worn, Acceptable 0,00

No pictures to display

Bumper F R, Scratch(es), It - Spot repair 115,56



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door frame F L, Scratch(es), 67 - Polish 0,00

No pictures to display

Door frame R L, Dent(s), It - Spot repair 115,56



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00



Door R L, Dent(s), PDR - Paintless dent repair 87,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68





Rearlight R , Broken, E - Replace

0,00

