



VOLKSWAGEN GOLF VARIANT: 1LLR589

| | | | |
|------------------------------------|--------------------------|--------------|-------------------------------|
| Vinnumber: | WVWZZZAUZGP543254 | Versionname: | 1.6 TDI 81KW TRENDLINE |
| First Registrationdate: | 21/10/2015 | Fiscalpower: | |
| Expertise Mileage: | 71658 | Power Kw: | 81 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 4610 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|---------------------------------|
| Radio CD | Central consol F |
| GPS storage | Luggage cover |
| GPS storage | SD Front parking sensors |
| Windows electric F | Rear parking sensors |
| Windows electric R | |
| Cruise Control | |
| Steering wheel multifunctional | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|-----------------------------|-------|-----------------------|-------|-----------------------|
| 195/65/15/92 H Steel | | | | |
| Summer tyres: | Fr.L. | Michelin: 5 mm | Fr.R. | Michelin: 5 mm |
| | Re.L. | Michelin: 6 mm | Re.R. | Michelin: 6 mm |

Assistance equipment

| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

| | |
|---|---------------|
| Total cost ex VAT | 597,47 |
| Bumper F L, Scratch(es), It - Spot repair | 115,56 |



Door R L, Dent(s), LI - Repair and paint (complete)

366,35



Bumper corner R R, Scratch(es), It - Spot repair

115,56



Roof, Dent(s), Acceptable

0,00

No pictures to display