



**BMW 5 TOURING: 1LLH770**

Vinnumber:	<b>WBA5L11000G323213</b>	Versionname:	<b>2.0 518D (110KW) TOURING</b>
First Registrationdate:	<b>20/10/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>96788</b>	Power Kw:	<b>110</b>
Bodytype:	<b>Break</b>	Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4402</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	<b>Headlighting Xenon</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining artificial leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>245/45/18/92 Y LightMetal</b>				
Summer tyres:	Fr.L.	<b>Pirelli: 4 mm</b>	Fr.R.	<b>Pirelli: 4 mm</b>
	Re.L.	<b>Pirelli: 5 mm</b>	Re.R.	<b>Pirelli: 5 mm</b>

**Assistance equipment**

Total cost ex VAT	733,16
Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), I - Repair	100,00



Bumper F, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Engine protective plate, Deformed / Strained, E - Replace	129,00
---	--------



Alloy rim R R, Scratch(es), I - Repair	100,00
--	--------




Roof, Dent(s), Acceptable	0,00
---------------------------	------

No pictures to display

Maintenance, Maintenance, P - Check	0,00
-------------------------------------	------



Alloy rim F R, Scratch(es), I - Repair	100,00
--	--------



Ceiling, Stain, Cleaning	50,00
--------------------------	-------



Bonnet, Dent(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Windscreen, Repaired, Acceptable	0,00
----------------------------------	------

