



**VOLVO V60: 1LB308**

Vinnnummer:	<b>YV1FW74C1G1292499</b>	Versionname:	<b>2.0 D2 KINETIC</b>
First Registrationdate:	<b>14/08/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>127300</b>	Power Kw:	<b>88</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2619</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		
Level control			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>215/55/16/97 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Vredestein: 5 mm</b>	Fr.R.	<b>Vredestein: 5 mm</b>
	Re.L.	<b>Vredestein: 6 mm</b>	Re.R.	<b>Vredestein: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT		95,00
-------------------	--	-------


Rocker panel inner F L, Dent(s), Acceptable		0,00
---	--	------

*No pictures to display*

Alloy rim R R, Scratch(es), Acceptable		0,00
--	--	------

*No pictures to display*

Bumper F, Scratch(es), Acceptable		0,00
-----------------------------------	--	------

<i>No pictures to display</i>		
Alloy rim R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Interior, Dirty, Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)		95,00
		
Windscreen, Stone chip(s), Acceptable		0,00
<i>No pictures to display</i>		
Bumper R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Centre console, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Outer door handle F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bonnet, Stone chip(s), Acceptable		0,00
<i>No pictures to display</i>		
Floor covering R, Worn, Acceptable		0,00
<i>No pictures to display</i>		