


FIAT DOBLO CARGO COMBI: SC6146

Vinnumber:	ZFA26300006J24451	Versionname:	1.3 Multijet 95 Combi SX SWB
First Registrationdate:	1/01/2021	Fiscalpower:	
Expertise Mileage:	39252	Power Kw:	70
Bodytype:		Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4313
Number of doors:	6		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/60/16/97 H Steel			
Winter tyres:	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Goodyear: 3 mm	Re.R.	Goodyear: 3 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1487,78
Wheel cover F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Full screen GPS, Not functioning (well), P - Check	0,00
<i>No pictures to display</i>	
Door F L, Dent(s), LI - Repair and paint (complete)	238,76



Boot carpet, Chemical pollution, E - Replace

75,00



Sliding door L, Dent(s), Le - Replace and paint

1088,52



Wing F L, Dent(s), PDR - Paintless dent repair

63,00



Wheel cover F R, Scratch(es), E - Replace

22,50

