


RENAULT CLIO: 1KPZ403

Vinnumber:	VF15R040H53388909	Versionname:	1.5 DCI 75 EXPRESSION
First Registrationdate:	12/06/2015	Fiscalpower:	
Expertise Mileage:	109733	Power Kw:	55
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4328
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/88 T Steel			
Summer tyres:	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Goodyear: 3 mm	Re.R.	Goodyear: 3 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1303,40
Wheel cover R R, Scratch(es), E - Replace	24,00



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

241,34



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

246,56



Door R R, Scratch(es), 67 - Polish

0,00

No pictures to display

Bonnet, Deformed / Strained, LI - Repair and paint (complete)

232,06



Wheel cover R L, Scratch(es), E - Replace

24,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44



Wheel cover F R, Scratch(es), E - Replace

24,00



Trunk lid covering R, Scratch(es), Smart repair

110,64



Mirror side blinker L, Broken, E - Replace

28,80




Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Wing F L, Bad repair, Acceptable

0,00



Wing F R, Scratch(es), 67 - Polish

0,00

No pictures to display

Windscreen, Repaired, Acceptable

0,00

Inspection, Repair(s), Acceptable

0,00



Wheel cover F L, Scratch(es), E - Replace

24,00



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Dent(s), PDR - Paintless dent repair

63,00

