



VOLVO S80: 1HYP437

Vinnumber:	VV1A531A1D1172854	Versionname:	S80 BER D3 Kinetic 136PK
First Registrationdate:	30/10/2014	Fiscalpower:	
Expertise Mileage:	117379	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2406
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Rear parking sensors	
GPS storage		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/98 H LightMetal				
Winter tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 8 mm	Re.R.	Michelin: 8 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			190,00
Door R L, Scratch(es), 67 - Polish			0,00



Windscreen, Stone chip(s), Windscreen repair

0,00



Bumper R, Scratch(es), 67 - Polish

0,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F R polished, Chemical polution, LI - Repair and paint (complete)

95,00



Alloy rim R L polished, Scratch(es), Acceptable

0,00

No pictures to display