



FORD TRANSIT CONNECT: 1VFF820

Vinnumber:	WF05XXWPGSJB68874	Versionname:	1.5 TDCi 88kW L2 Trend
First Registrationdate:	22/10/2018	Fiscalpower:	
Expertise Mileage:	40942	Power Kw:	88
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2624
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Rear parking sensors	
GPS storage	HD	Type of Tow bar	No Tow bar
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

	205/60/16/96 H Steel			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		


Total cost ex VAT	622,84
Wing F R, Chemical polution, LI - Repair and paint (complete)	165,13



Trunk door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Instrument panel cover, Not original part, Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Scratch(es), 67 - Polish	0,00
<i>No pictures to display</i>	
Bumper F, Scratch(es), LI - Repair and paint (complete)	158,85



Bonnet, Scratch(es), LI - Repair and paint (complete)	217,56
---	--------



Windscreen, Stone chip(s), Windscreen repair	58,80
--	-------



Roof pillar R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Scratch(es), 67 - Polish	0,00
<i>No pictures to display</i>	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 22,50

