


**SKODA OCTAVIA COMBI: 1LVU920**

|                                    |                          |              |  |
|------------------------------------|--------------------------|--------------|--|
| Vinnumber:                         | <b>TMBJG9NE4G0134190</b> | Versionname: | <b>1.6 CRTDI 81KW DSG 7 GREENTEC STYLE</b> |
| First Registrationdate:            | <b>18/12/2015</b>        | Fiscalpower: |  |
| Expertise Mileage:                 | <b>124625</b>            | Power Kw:    | <b>81</b>                                  |
| Bodytype:                          |                          | Body color:  | <b>Grey</b>                                |
| Gearbox:                           | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>                             |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                           |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                                  |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2303</b>                                |
| Number of doors:                   | <b>5</b>                 |              |  |
| Number of seats:                   | <b>5</b>                 |              |  |
| Number head rests:                 | <b>5</b>                 |              |  |
| Rims summer:                       | <b>Aluminium</b>         |              |  |
| Category:                          | <b>Passenger Car</b>     |              |  |
| Oil level:                         | <b>OK</b>                |              |  |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |  |

**Options**

|                                |                                       |                          |
|--------------------------------|---------------------------------------|--------------------------|
| Windows electric F             | Seats electric F L                    |                          |
| Windows electric R             | Central consol F                      |                          |
| Cruise Control                 | Luggage cover                         |                          |
| Steering wheel multifunctional | Front parking sensors                 |                          |
| Seats F heated                 | Rear parking sensors                  |                          |
| Radio multimedia               | Type of Tow bar                       | <b>Tow bar removable</b> |
| Type of headlighting           | <b>Headlighting Xenon</b>             |                          |
| Type of GPS                    | <b>GPS big screen color</b>           |                          |
| Type of Lining                 | <b>Lining semi-artificial leather</b> |                          |
| Type of climate control        | <b>Autom climate control</b>          |                          |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>225/45/17/97 W LightMetal</b> |                          |       |                          |
| Summer tyres: | Fr.L.                            | <b>Continental: 4 mm</b> | Fr.R. | <b>Continental: 4 mm</b> |
|               | Re.L.                            | <b>Continental: 4 mm</b> | Re.R. | <b>Continental: 4 mm</b> |

**Assistance equipment**

|  |            |            |            |
|--|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

|   |               |
|---|---------------|
| Total cost ex VAT                                       | <b>211,80</b> |
| Bumper F, Scratch(es), Acceptable                       | <b>0,00</b>   |
| <i>No pictures to display</i>                           |               |
| Bumper R, Scratch(es), LI - Repair and paint (complete) | <b>211,80</b> |



Door R L, Scratch(es), Acceptable

0,00

*No pictures to display*