



NISSAN X-TRAIL: 62930

| | | | |
|------------------------------------|--------------------------|--------------|------------------|
| Vinnumber: | JN1TCAT32U0054335 | Versionname: | |
| First Registrationdate: | 1/01/2020 | Fiscalpower: | |
| Expertise Mileage: | 34605 | Power Kw: | |
| Bodytype: | | Body color: | Black |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | 4 Weel | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 4721 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | No | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD | | Sun Roof electric | |
| GPS storage | SD | Panoramic roof | |
| GPS storage | | Central consol F | |
| Windows electric F | | Luggage cover | |
| Windows electric R | | Front parking sensors | |
| Cruise Control | | Rear parking sensors | |
| Steering wheel multifunctional | | Type of Tow bar | No Tow bar |
| Seats F heated | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting LED | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| 225/55/19/99 V LightMetal | | | | |
| Summer tyres: | Fr.L. | Goodyear: 8 mm | Fr.R. | Goodyear: 8 mm |
| | Re.L. | Goodyear: 7 mm | Re.R. | Goodyear: 7 mm |

Assistance equipment

| | | | |
|--|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|--|---------------|
| Total cost ex VAT | 281,12 |
| Bumper R, Dent(s) and scratch(es), It - Spot repair | 115,56 |



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 50,00



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Door frame F L, Scratch(es), It - Spot repair 115,56

