



**VOLVO V40: 1HTC470**

|                                    |                          |              |                                     |
|------------------------------------|--------------------------|--------------|-------------------------------------|
| Vinnumber:                         | <b>YV1MZ8451F2064043</b> | Versionname: | <b>V40 Cr.Country D2 Base 115PK</b> |
| First Registrationdate:            | <b>25/09/2014</b>        | Fiscalpower: |                                     |
| Expertise Mileage:                 | <b>105330</b>            | Power Kw:    | <b>84</b>                           |
| Bodytype:                          |                          | Body color:  | <b>Black</b>                        |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                      |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                    |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                           |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>4728</b>                         |
| Number of doors:                   | <b>5</b>                 |              |                                     |
| Number of seats:                   | <b>5</b>                 |              |                                     |
| Number head rests:                 | <b>5</b>                 |              |                                     |
| Rims summer:                       | <b>Aluminium</b>         |              |                                     |
| Category:                          | <b>Passenger Car</b>     |              |                                     |
| Oil level:                         | <b>OK</b>                |              |                                     |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                     |

**Options**

|                                |                               |                      |                      |
|--------------------------------|-------------------------------|----------------------|----------------------|
| Radio CD                       |                               | Panoramic roof       |                      |
| GPS storage                    |                               | Central consol F     |                      |
| GPS storage                    | <b>HD</b>                     | Luggage cover        |                      |
| Windows electric F             |                               | Rear parking sensors |                      |
| Windows electric R             |                               | Type of Tow bar      | <b>Tow bar fixed</b> |
| Cruise Control                 |                               |                      |                      |
| Steering wheel multifunctional |                               |                      |                      |
| Seats F heated                 |                               |                      |                      |
| Radio multimedia               |                               |                      |                      |
| Type of headlighting           | <b>Headlighting Halogen</b>   |                      |                      |
| Type of GPS                    | <b>GPS big screen color</b>   |                      |                      |
| Type of Lining                 | <b>Lining fabrics</b>         |                      |                      |
| Type of climate control        | <b>Manual climate control</b> |                      |                      |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>205/60/16/92 H LightMetal</b> |                       |       |                       |
| Winter tyres: | Fr.L.                            | <b>Goodyear: 5 mm</b> | Fr.R. | <b>Goodyear: 5 mm</b> |
|               | Re.L.                            | <b>Goodyear: 5 mm</b> | Re.R. | <b>Goodyear: 5 mm</b> |

**Assistance equipment**

|  |            |            |            |
|--|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

Total cost ex VAT 520,00

Bonnet, Chemical polution, 67 - Polish 0,00

No pictures to display

Wing F L, Chemical polution, 67 - Polish 0,00

|   |        |
|---|--------|
| <i>No pictures to display</i>                                       |        |
| Door R R, Scratch(es), Acceptable                                   | 0,00   |
| <i>No pictures to display</i>                                       |        |
| Bumper F, Scratch(es), Acceptable                                   | 0,00   |
| <i>No pictures to display</i>                                       |        |
| Door F R, Scratch(es), Acceptable                                   | 0,00   |
| <i>No pictures to display</i>                                       |        |
| Rear spoiler, Scratch(es), Acceptable                               | 0,00   |
| <i>No pictures to display</i>                                       |        |
| Door F L, Scratch(es), Acceptable                                   | 0,00   |
| <i>No pictures to display</i>                                       |        |
| Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) | 308,20 |



|   |        |
|---|--------|
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|

