



RENAULT ESPACE: 1LSU810

Vinnumber:	VF1RFC00854317661	Versionname:	1.6 DCI 130 ENERGY INTENS
First Registrationdate:	25/11/2015	Fiscalpower:	
Expertise Mileage:	71344	Power Kw:	96
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2212
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Alarm			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/60/18/107 H LightMetal				
Winter tyres:	Fr.L.	Fulda: 7 mm	Fr.R.	Fulda: 7 mm
	Re.L.	Fulda: 7 mm	Re.R.	Fulda: 7 mm

Assistance equipment

Emergency spare wheel	Yes
-----------------------	------------

Total cost ex VAT	949,36
-------------------	---------------

Gear shift lever cover, Worn, Acceptable	0,00
--	-------------



Wing F L, Scratch(es), Acceptable

0,00



Bumper moulding F R, Scratch(es), E - Replace

48,00



Bonnet, Stone chip(s), Acceptable

0,00



Tailgate, Scratch(es), Acceptable

0,00



Tailgate, Not original part, Sticker removal

25,00



Door F L, Scratch(es), Acceptable

0,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Interior, Smell, Ozone treatment

152,58

No pictures to display

Seat cover F L, Worn, Acceptable

0,00



Sill outer R, Scratch(es), It - Spot repair

115,56



Bumper moulding R, Scratch(es), Smart repair

110,64



Bumper F, Scratch(es), Acceptable

0,00



Door R R, Scratch(es), It - Spot repair

115,56



Wing R L, Dent(s), Acceptable

0,00

