



VOLKSWAGEN Golf: 1FWF210

Vinnumber:	WVWZZZAUZEW163614	Versionname:	GOLF BER Trendline 90PK
First Registrationdate:	15/11/2013	Fiscalpower:	
Expertise Mileage:	106120	Power Kw:	66
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1232
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

	195/65/15/91 V Steel			
Summer tyres:	Fr.L.	BF Goodrich: 4 mm	Fr.R.	BF Goodrich: 4 mm
	Re.L.	BF Goodrich: 4 mm	Re.R.	BF Goodrich: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	285,80
Wheel cover F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Protection plate M, Deformed / Strained, E - Replace	74,00
--	-------



Bonnet, Chemical pollution, Acceptable	0,00
--	------

No pictures to display

Door R R, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display