



Audi TT: 1PLD762

Vinnumber:	TRUZZFV1F1010033	Versionname:	
First Registrationdate:	1/08/2016	Fiscalpower:	
Expertise Mileage:	58787	Power Kw:	169
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1121
Number of doors:	3		
Number of seats:	4		
Number head rests:	0		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-Alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

245/35/19/93 Y LightMetal				
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 2726,61

Alloy rim R R polished, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete) 372,60



Roof, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), LI - Repair and paint (complete) 382,02



Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Wing R L, Scratch(es), 67 - Polish 0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 369,84



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00





Sill outer R, Scratch(es), LI - Repair and paint (complete)

372,60



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

362,02



Wing F R, Scratch(es), LI - Repair and paint (complete)

264,21



Door panel R L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Rearview mirror housing R, Scratch(es), 67 - Polish

0,00

No pictures to display

Bonnet, Chemical polution, 67 - Polish

0,00

0,00		
<i>No pictures to display</i>		
Door F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Roof pillar R, Scratch(es), 67 - Polish		0,00
<i>No pictures to display</i>		