



LU AUDI a3 Limousine: UK8796

Vinnumber:	WAUZZZ8V2J1031857	Versionname:	1.0 TFSI 85kW
First Registrationdate:	22/11/2017	Fiscalpower:	
Expertise Mileage:	67850	Power Kw:	85
Bodytype:		Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Maintenance:	DANS 22100 KMS OU 367 JOURS	Parking lot:	2822
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Rear parking sensors	
GPS storage	SD	Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Level control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 W LightMetal			
Summer tyres:	Fr.L. Bridgestone: 3 mm	Fr.R. Bridgestone: 3 mm	
	Re.L. Michelin: 7 mm	Re.R. Michelin: 7 mm	

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT 309,32

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Bodywork, Dirty, P - Check 0,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display


Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Seat cover F L, Damaged, Smart repair 64,32



Interior, Dirty, Cleaning 150,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Certificate Of Conformity, Missing, P - Check 0,00



Roof pillar L, Scratch(es), Acceptable

0,00

No pictures to display