



**Audi A3: 1LTV771**

|                                    |                          |              |                  |
|------------------------------------|--------------------------|--------------|------------------|
| Vinnumber:                         | <b>WAUZZZ8V6GA077815</b> | Versionname: |                  |
| First Registrationdate:            | <b>3/12/2015</b>         | Fiscalpower: |                  |
| Expertise Mileage:                 | <b>75931</b>             | Power Kw:    | <b>81</b>        |
| Bodytype:                          |                          | Body color:  | <b>Grey</b>      |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>   |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b> |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>        |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>4826</b>      |
| Number of doors:                   | <b>5</b>                 |              |                  |
| Number of seats:                   | <b>5</b>                 |              |                  |
| Number head rests:                 | <b>5</b>                 |              |                  |
| Rims summer:                       | <b>Aluminium</b>         |              |                  |
| Category:                          | <b>Passenger Car</b>     |              |                  |
| Oil level:                         | <b>OK</b>                |              |                  |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                  |

**Options**

|                                |                              |                   |
|--------------------------------|------------------------------|-------------------|
| Radio CD                       | Central consol F             |                   |
| Windows electric F             | Luggage cover                |                   |
| Windows electric R             | Rear parking sensors         |                   |
| Cruise Control                 | Type of Tow bar              | <b>No Tow bar</b> |
| Steering wheel multifunctional |                              |                   |
| Seats F heated                 |                              |                   |
| Radio multimedia               |                              |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                   |
| Type of Lining                 | <b>Lining leather</b>        |                   |
| Type of climate control        | <b>Autom climate control</b> |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                     |       |                     |
|----------------------------------|-------|---------------------|-------|---------------------|
| <b>205/55/16/91 H LightMetal</b> |       |                     |       |                     |
| Winter tyres:                    | Fr.L. | <b>Kleber: 5 mm</b> | Fr.R. | <b>Kleber: 5 mm</b> |
|                                  | Re.L. | <b>Kleber: 5 mm</b> | Re.R. | <b>Kleber: 5 mm</b> |

**Assistance equipment**

|  |            |            |            |
|--|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>00</b>  |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

|  |               |
|--|---------------|
| <b>Total cost ex VAT</b>                                       | <b>668,60</b> |
| <b>Bumper R, Scratch(es), LI - Repair and paint (complete)</b> | <b>211,80</b> |



|  |       |
|--|-------|
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|



|   |        |
|---|--------|
| Bumper F, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|



|  |      |
|--|------|
| Alloy rim F L, Scratch(es), Acceptable | 0,00 |
|--|------|

*No pictures to display*

|                                    |        |
|------------------------------------|--------|
| Ignition key, Missing, E - Replace | 150,00 |
|------------------------------------|--------|

*No pictures to display*