



**AUDI Q5: 1LER089**

Vinnumber:	<b>WAUZZZ8R7GA043465</b>	Versionname:	<b>2.0 TFSI 165KW TIPTRONIC QUATTRO</b>
First Registrationdate:	<b>7/09/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>50278</b>	Power Kw:	<b>165</b>
Bodytype:		Body color:	<b>ROOD</b>
Gearbox:	<b>Automatic</b>	Body color:	<b>Red</b>
Transmission:	<b>4 Weel</b>	Paint type:	<b>Metalic</b>
Fueltype:	<b>Petrol</b>	Rims summer:	<b>Aluminium</b>
Maintenance:	<b>OK</b>	Oil level:	<b>OK</b>
Maintenance:	<b>6500 KM</b>	Parking lot:	<b>4101</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		
Sport seats			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>235/65/17/104 W LightMetal</b>			
Summer tyres:	Fr.L. <b>Michelin: 5 mm</b>	Fr.R. <b>Michelin: 5 mm</b>	
	Re.L. <b>Michelin: 5 mm</b>	Re.R. <b>Michelin: 5 mm</b>	

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT 254,16

Wing F L, Repaired, No repair 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bonnet, Not original part, Acceptable	0,00
---------------------------------------	------



Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bonnet, Repaired, No repair	0,00
-----------------------------	------

No pictures to display