


AUDI Q5: 1LUY377

Vinnnumber:	WAUZZZ8R0GA051214	Versionname:	2.0 TDI 100KW
First Registrationdate:	11/12/2015	Fiscalpower:	
Expertise Mileage:	145368	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3627
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	Headlighting LED
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/65/17/92 MS LightMetal			
Winter tyres:	Fr.L.	Other: 5 mm	Fr.R.	Other: 5 mm
	Re.L.	Other: 6 mm	Re.R.	Other: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			342,66
Bumper F R, Scratch(es), It - Spot repair			115,56



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Chemical polution, 67 - Polish

0,00



Rearlight R , Broken, E - Replace

132,10



Rearview mirror housing L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), Acceptable

0,00

No pictures to display