


Ford FOCUS: 1VTQ890

| | | | |
|------------------------------------|--------------------------|--------------|--------------------|
| Vinnumber: | WF0NXXGCHNKK47427 | Versionname: | |
| First Registrationdate: | 26/02/2019 | Fiscalpower: | |
| Expertise Mileage: | 25548 | Power Kw: | 74 |
| Bodytype: | | Body color: | Blue |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Petrol | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | PARKING A12 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|-------------------------------|-----------------------|-------------------|
| GPS storage | | Central consol F | |
| GPS storage | HD | Luggage cover | |
| Windows electric F | | Front parking sensors | |
| Windows electric R | | Rear parking sensors | |
| Cruise Control | | Type of Tow bar | No Tow bar |
| Steering wheel multifunctional | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Manual climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| 205/60/16/96 V LightMetal | | | | |
|---------------------------|-------|----------------|-------|----------------|
| Winter tyres: | Fr.L. | Michelin: 4 mm | Fr.R. | Michelin: 4 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | |
|--|------------|
| Emergency spare wheel | Yes |
| Number of charging cables (normal) | 0 |
| Number of charging cables (rapid charge) | 0 |

| | |
|------------------------------------|------|
| Total cost ex VAT | 0,00 |
| Door F R, Scratch(es), 67 - Polish | 0,00 |
| <i>No pictures to display</i> | |
| Door F L, Repaired, Acceptable | 0,00 |
| <i>No pictures to display</i> | |