



**MERCEDES Vito: 1ET1991**

Vinnumber:	<b>WDF63960113803808</b>	Versionname:	<b>VITO 110 B/F SWB 95PK</b>
First Registrationdate:	<b>15/03/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>194155</b>	Power Kw:	<b>70</b>
Bodytype:		Body color:	<b>Red</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4811</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>4</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Central consol F	
Windows electric F		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	<b>Headlighting Halogen</b>	Type of Tow bar	<b>No Tow bar</b>
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/65/16/104 T Steel</b>			
Winter tyres:	Fr.L.	<b>Semperit: 9 mm</b>	Fr.R.	<b>Semperit: 9 mm</b>
	Re.L.	<b>Semperit: 9 mm</b>	Re.R.	<b>Semperit: 9 mm</b>

**Assistance equipment**

Spare wheel	<b>No</b>	Jack	<b>No</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>1232,74</b>
<b>Door F R, Dent(s), It - Spot repair</b>	<b>115,56</b>



Bodywork, Not original part, Acceptable

0,00



Tailgate, Scratch(es), LI - Repair and paint (complete) 362,02




Sidewall FL (LCV), Dent(s), It - Spot repair 259,56



Jack, Missing, E - Replace 42,00

*No pictures to display*

Seat cover F L, Damaged, E - Replace 300,00



Sliding door R, Scratch(es), Acceptable 0,00

*No pictures to display*

Spare wheel, Missing, E - Replace 153,60

