



MERCEDES GLA: 1KVR440

Vinnumber:	WDC1569081J145355	Versionname:	2.1 GLA 200 CDI STYLE
First Registrationdate:	15/07/2015	Fiscalpower:	
Expertise Mileage:	150824	Power Kw:	100
Bodytype:	Hatchback	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2123
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/17/96 H LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1023,86
Wing trim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper Trim F, Dent(s) and scratch(es), E - Replace	220,10



Wing moulding F L, Scratch(es), E - Replace	17,28
---	-------



Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rocker panel inner R R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Bumper corner R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Floor covering F L, Burned, Smart repair	64,32
--	-------



Sill outer R, Deformed / Strained, Forfeit	348,00
--	--------



Bonnet, Chemical pollution, Acceptable	0,00
--	------

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	374,16
---	--------

