



**OPEL ZAFIRA TOURER: 1LJP914**

Vinnumber:	<b>WOLPE9E38G1015940</b>	Versionname:	<b>1.6 CDTI ECOFLEX 100KW S/S COSMO</b>
First Registrationdate:	<b>6/10/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>62253</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3522</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining semi-artificial leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>215/60/16/92 H LightMetal</b>			
Summer tyres:	Fr.L.	Fr.R.	Continental: 4 mm
	Re.L.	Re.R.	Continental: 5 mm

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	1359,55
Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08



Bumper F L, Scratch(es), It - Spot repair

115,56



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Wing R L, Scratch(es), Acceptable

0,00

*No pictures to display*

Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20



Rocker panel inner R L, Scratch(es), Forfeit

115,56



Door R R, Scratch(es), LI - Repair and paint (complete)

318,35

